

NTY - SPK-MS-005 - Cremallera dirección Mitsubishi Montero

OEM: 4410A139 Mitsubishi

Para Mitsubishi Montero y Pajero





 MITSUBISHI MONTERO IV (V8_W, V9_W) [10/2006 a ...] 3.2 DI-D 4WD (V98W, V88W) 190cv 140kw 4M41

 MITSUBISHI MONTERO IV (V8_W, V9_W) [10/2006 a ...] 3.2 DI-D 4WD (V98W, V88W) 200cv 147kw 4M41

 MITSUBISHI MONTERO IV (V8_W, V9_W) [10/2006 a ...] 3.2 DI-D (V88W, V98W) 160cv 118kw 4M41

 MITSUBISHI MONTERO IV (V8_W, V9_W) [10/2006 a ...] 3.2 DI-D (V88W, V98W) 170cv 125kw 4M41

 MITSUBISHI MONTERO IV (V8_W, V9_W) [10/2006 a ...] 3.8 V6 (V87W, V97W) 250cv 184kw 6G75

 MITSUBISHI PAJERO IV (V8_W, V9_W) [10/2006 a ...] 3.2 DI-D 4WD (V98W, V88W) 190cv 140kw 4M41

 MITSUBISHI PAJERO IV (V8_W, V9_W) [10/2006 a ...] 3.2 DI-D 4WD (V98W, V88W) 200cv 147kw 4M41

